

RBC SERVICES UPDATE

RBC Services
Division of McNish Corporation

Phone: 630-264-5241 Fax: 630-892-7951

RBC REPLACEMENT PARTS

Issue 1, 1992

SideCar AERATION SYSTEMS

FLEXCAP COARSE BUBBLE DIFFUSERS

V-BELTS

DRIVE SHEAVES, MOTOR & REDUCER

CHAIN DRIVE REDUCERS

SHAFT MOUNT DRIVE REDUCERS

LARGE DRIVEN SPROCKETS

DRIVE SPROCKETS

DRIVE CHAIN

CHAIN CASES

CHAIN CASE SEALS

LOAD CELL KITS

SHAFT LIFTING DEVICES

AIR CUPS

MEDIA SUPPORT STRUCTURES

MEDIA

SHAFTS

MAIN SHAFT BEARINGS

If your equipment needs go beyond those listed above for Autotrol/Envirex, LYCO & Walker RBCs, **DON'T PANIC!** If we don't have what you need, we'll turn you onto someone who does. **EITHER WAY - YOU'RE COVERED!**

Although RBC Services is a small organization, we live up to our name when it comes to service and support for RBC owners and operators. We have the experience to understand your needs and provide you with information on repair procedures and quality replacement parts, whether it's a visit to your plant or a call to our office.

We will do what it takes to help you with your needs and handle any problem so the only headache you may have is on Sunday morning.

Please remember...along with any RBC equipment, we handle a complete line of replacement components for rectangular clarifiers: Chain. Sprockets. Wear Shoes. Flights. Wear Strips. Chain and sprockets are available in either metallic or non-metallic types. Regardless of whose name is on the drawing, our components are high quality, competitively priced...and in most every case, they're compatible.

If you ever have any questions regarding your RBC operations, please do not hesitate to give me a call. We are as near as you phone to assist in any way possible.